



Model

Parameters Run Reset

- Tormach
- Roughing waterline
- Finishing drive
- Finishing combine

2D Geometry

Machining

Simulation

Setup

Main parameters

- Approach/Return
 - Approach reference po: Short
 - Return reference point: Short
 - Tool change position: From the previous op
 - Workpiece setup: From the previous op
 - Workpiece CS: From the previous op
 - Local CS: Off
- Rotary Axis
 - A (Axis A Position)
- Linear Axis
 - X (Axis X Position)
 - XX (Rotary Table Position)
 - Y (Axis Y Position)
 - Z (Axis Z Position)

Tools list Postprocessor

