



# Logitech 3D Extreme Pro Hall Effect Sensor Mod Wiring Diagram



1. X and Y Axis pot connector
  - a. Red – Voltage Supply
  - b. Green – X-Axis Signal
  - c. White – Y-Axis Signal
  - d. Black – Ground
2. Throttle and Non-Stick Buttons Connector
  - a. Red – Throttle Voltage Supply
  - b. Green – Throttle Signal
  - c. White – Throttle Ground
  - d. Everything else – not important
3. Stick Pot and Buttons Connector
  - a. Blue (Far Left) – Z-Axis (Rudder) Voltage Supply
  - b. Black – Z-Axis (Rudder) Signal
  - c. Brown – Z-Axis (Rudder) Ground
  - d. Everything else – not important
4. USB connector
  - a. Green – Unknown (Data)
  - b. White – Unknown (Data)
  - c. Red – 5V Supply
  - d. Black – Ground
  - e. Large Black – Shield

