

### Pterodactyl Parts

Name	Count	Infill	Raft	Brim	Support
Arm Wing Tip.stl	2	20%	No	No	No
Arm Yoke.stl	4	20%	No	No	No
Axle Gear 20 Teeth.stl	1	20%	No	No	No
Axle Wing Center.stl	1	20%	No	Yes	No
Axle Wing Tip.stl	2	20%	No	Yes	No
Base.stl	1	20%	No	No	Optional
Bellcrank.stl	2	20%	No	No	No
Body.stl	1	20%	No	No	No
Cam.stl	2	20%	Yes	No	No
Crank Bolt.stl	1	20%	No	Yes	No
Crank Knob.stl	1	20%	No	Yes	No
Knurled 6mm.stl	12	20%	No	No	No
Pin Cam.stl	2	20%	No	No	No
Slide.stl	2	20%	No	No	No
Spur Gear (20 teeth).stl	1	20%	Yes	No	No
Spur Gear (40 teeth).stl	1	20%	Yes	No	No
Wing Left Root.stl	1	20%	No	No	No
Wing Left Tip.stl	1	20%	No	No	No
Wing Right Root.stl	1	20%	No	No	No
Wing Right Tip.stl	1	20%	No	No	No
Yoke.stl	2	20%	No	No	No
<b>Total</b>	<b>42</b>				