

nuts for each screw.

Attach the Spring Body Mount Plate to the Back Plate using 4 #6 x3/4" round head wood screws.

Motor

Motor Transfer Plate

Spring Body Mount plate

Upper Body Assembly

2 nuts for each screw.

Materials:

2 #6-32 x 1/2" round head screws, washers and two

- 1- Body Plate
- 1- Worm Gear
- 1- Worm Gear Carriage (Assembly)
- 1- Spring Body Mount Plate
- 1- Motor
- 1- Motor Transfer Plate

- 3-#6-32 x3/4" flat head machine screws
- 4- #6 x4/4" round head wood screws
- 2-#6-32 x 1/2" round head machine screws
- 5- #6 flat washers
- 10-#6-32 nuts