




Use correct connections based on your sensor!



Four matrix display



Power from USB with a 5V charger from a cellPhone or use the 12V power input

