



CORRECT FOR NEXT RELEASE: BUTTON IS ON WRONG SIDE!!!  
 BATTERY CLIP OVER TRACES!!  
 power rail cap does not fit  
 battery clip holes slightly small  
 LDO reg would improve to feed the ADXL

Title		
Size A4	Number	Revision
Date: 2017. 01. 27.	Sheet of	
File: C:\Users\...\villogo.SchDoc	Drawn By:	

